

Press SET – TEMPERATURE WILL DISPLAY – THIS IS THE “SET POINT”
Possibly will display 4.

Hold SET until PS shows

Press SET again – will display O. Using up and down keys select 22 (PASSWORD)

Press SET again – PS will display again
Use up/down keys to locate rd (PARAMETER)

Press SET again – Using up/down keys select 3

Press SET again – Using up/down keys select r3

Press SET again – Using up/down keys select 2

Press SET again – r3 will display again

Press SET and hold button until display returns to normal

Press SET again and that will display SET POINT once more

Use up and down arrows to change to 75

Press SET and it will return to normal