




LSMT GANTRY ASSEMBLED



EXPLODED TROLLEY DIAGRAM

- Do not overtighten bolts and screw fixings



1.

Place the bottom section in a clear space and lock the castors during assembly.

2.

Slide the end posts and mid posts into position and tighten screws and bolts.



3.

Tighten screws and bolts securely.

4.

Lift on the top section and fix screws on each post.



5. Place base shelves in the frame.

6. Attach the side and end panels by pushing up and over the fixing clip rails top and bottom. Pull down to secure.